

Product Firmware Update Requirements for Break Out Box (BOBe version)

The following InterMotive products will require updated firmware to be compatible with BOBe:

- GTWY505 / HL510 v4.59 or higher
- GTWY506 / HL550 / WTSI506 v4.61 or higher
- GTWY605 / HL610 v4.59 or higher
 - NOTE: All other GTWY / HL products will have BOBe compatibility
- PRC5xx v4.46 or higher
- AIM514, AIM515, AIM516, AIM517 and AIM518: All versions; must use the latest version of BOBe or fast idle will be impacted.
- DLM506, DLM507: All versions; must be connected to the unprotected side in order to wake the vehicle network.
- WTDL750 and WTDL751: All versions; must be connected to the unprotected side so in order to wake the vehicle network.